## IN THE SPECIFICATION

On page 13, replace the paragraph spanning lines 6 to 10 by the following paragraphs:

"Figs. 1A and 1B illustrates illustrate four days after implantation of MSC into the myocardium: Top panel: Hematoxylin with hematoxylin and eosin stain (Fig. 1A) and with; Lower panel: Fluorescent fluorescent microscopy picture, showing MSCs labeled with DAPI (Fig. 1B);

Figs 2A and 2B illustrates illustrate four weeks post-implantation of MSC into the myocardium with hematoxylin and eosin stain (Fig. 2A) and with fluorescent microscopy, showing MSCs labelled with DAP1 (Fig 2B)";